

Table 2.1 Requirements for minor passively ventilated vents in high level waste tank farms

Perform Periodic Confirmatory Measurements (PCM) annually by verifying the levels of smearable contamination on the inside surface of the ducting and downstream of the HEPA filter, or on the outside of the screen covering the outlet of the vent, should one exist. Use a confirmation level below 10,000 dpm/100cmsq beta gamma and 200 dpm/cmsq alpha to verify low emissions. Detective levels above these thresholds would result in further investigation and reporting if it is determined that the cause was due to an airborne emission. The radiological survey reports will become the record for the PCM. [WAC 173-401-615(2)]

P-244A-002	738	P-241A101-001	92
P-241A103-001	87	P-241A104-001	88
P-241A106-001	94	P-241AX101-001	305
P-241AX103-001	304	P-241AX104-001	302
P-241B102-001	270	P-241B103-001	279
P-241B105-001	266	P-241B106-001	281
P-241B108-001	268	P-241B109-001	277
P-241B111-001	276	P-241B112-001	274
P-241B202-001	280	P-241B203-001	282
P-241BX101-001	259	P-241BX102-001	262
P-241BX104-001	255	P-241BX105-001	273
P-241BX107-001	258	P-241BX108-001	265
P-241BX110-001	256	P-241BX111-001	264
P-241BY101-001	283	P-241BY102-001	286
P-241BY104-001	289	P-241BY105-001	284
P-241BY107-001	294	P-241BY108-001	291
P-241BY110-001	293	P-241BY111-001	292
P-241C101-001	247	P-241C102-001	237
P-241C107-001	230	P-241C108-001	231
P-241C110-001	244	P-241C111-001	1
P-241C201-001	233	P-241C202-001	246
P-241C204-001	235	P-241S101-001	132
P-241S104-001	131	P-241S105-001	137
P-241S107-001	140	P-241S108-001	135
P-241S110-001	138	P-241S111-001	202
P-241SX115-001	200	P-241T101-001	79
P-241T103-001	78	P-241T104-001	71
P-241T106-001	66	P-241T107-001	69

Table 2.1 Requirements for minor passively ventilated vents in high level waste tank farms

Perform Periodic Confirmatory Measurements (PCM) annually by verifying the levels of smearable contamination on the inside surface of the ducting and downstream of the HEPA filter, or on the outside of the screen covering the outlet of the vent, should one exist. Use a confirmation level below 10,000 dpm/100cmsq beta gamma and 200 dpm/cmsq alpha to verify low emissions. Detective levels above these thresholds would result in further investigation and reporting if it is determined that the cause was due to an airborne emission. The radiological survey reports will become the record for the PCM. [WAC 173-401-615(2)]

P-241T109-001	67	P-241T110-001	76
P-241T112-001	72	P-241T201-001	80
P-241T203-001	74	P-241T204-001	75
P-241TX102-001	124	P-241TX103-001	120
P-241TX105-001	116	P-241TX106-001	126
P-241TX108-001	123	P-241TX109-001	128
P-241TX111-001	130	P-241TX112-001	115
P-241TX114-001	119	P-241TX115-001	125
P-241TX117-001	113	P-241TX118-001	129
P-241TY102-001	82	P-241TY103-001	85
P-241TY105-001	83	P-241TY106-001	81
P-241U102-001	101	P-241U103-001	97
P-241U105-001	112	P-241U106-001	111
P-241U108-001	98	P-241U109-001	105
P-241U111-001	107	P-241U112-001	108
P-241U202-001	106	P-241U203-001	100